
PART 2 – DETAILED VISUAL INSPECTION



FigureA.1 (k) Pot Bearing

Condition State: Poor	Performance Deficiency: Seized Bearings
Stainless sliding surface debonded from shoe plate.	Bearing transferring unintended forces to substruction

PART 2 – DETAILED VISUAL INSPECTION



FigureA.1 (I) Steel Rocker Bearing

Condition State: Fair	Performance Deficiency: Bearing Not Uniformly Loaded/Unstable
Medium Corrosion.	Rocker corrosion products causing rocker to tilt more than warranted for inspection temperature. Alignment bolts severely corroded, filling slots in rocker with debris, limiting movement.

PART 2 – DETAILED VISUAL INSPECTION



FigureA.1 (m) Steel Rocker Bearing

Condition State: Poor Severe corrosion and section loss of rocker, with excessive buildup of debris on contact surfaces. No evidence of bearing movement.	Performance Deficiency: Bearing Seized Expansion bearing at abutment causing redistribution of expansion/contraction forces.
---	--

PART 2 – DETAILED VISUAL INSPECTION



Figure A.1 (n) Roller Bearing

Condition State: Poor	Performance Deficiency: Seized Bearings
Very severe corrosion, debris filling space between rollers, alignment plate missing.	Rollers frozen with no capability for movement. Alignment of rollers compromised.

PART 2 – DETAILED VISUAL INSPECTION



Figure A.1 (p)Concrete Wingwall

Condition State: Poor	Performance Deficiency: None
Wide Cracks and crushing of concrete	Deck appears to be crushing wingwall with expansion movements. Monitor.

PART 2 – DETAILED VISUAL INSPECTION

A.2 APPROACHES



Figure A.2 (a) Concrete Approach Slab

<p>Condition State: Good</p>	<p>Performance Deficiency: Pedestrian/Vehicular Hazard / Rough Riding Surface</p>
<p>No visible defects in approach slab</p>	<p>Approach has settled by 125-150 mm adjacent to the bridge, causing lift axle tires to ground-out over joint.</p>

PART 2 – DETAILED VISUAL INSPECTION



Figure A.2 (a new) Concrete Approach Slab

Condition State: Good	Performance Deficiency: Pedestrian/Vehicular Hazard / Rough Riding Surface
No visible defects in approach slab	Approach has settled by 25mm adjacent to the bridge, causing rough ride and tripping hazard.

PART 2 – DETAILED VISUAL INSPECTION



FigureA.2 (b) Approach: Concrete Sidewalk

Condition State: Poor	Performance Deficiency: None
Severe spall	

PART 2 – DETAILED VISUAL INSPECTION



Figure A.2 (c) Wood Curb

Condition State: Good	Performance Deficiency: None
Light Checks	Satisfactory curb height, with no displacements or projections

PART 2 – DETAILED VISUAL INSPECTION



FigureA.2 (d) Concrete Sidewalk

Condition State: Poor	Performance Deficiency: Pedestrian/Vehicular Hazard
Severe spalling with exposed corroded reinforcement	Sidewalk surface irregular with large spalls presenting difficulty for pedestrian passage

PART 2 – DETAILED VISUAL INSPECTION

A.3 BARRIERS

Figure A.3 (a) Parapet Wall

Parapet Wall

Condition State: Poor	Performance Deficiency: None
Wide stained cracks, large delaminations and spalls with exposed rebar	No performance defects

Hand Railing

Condition State: Good	Performance Deficiency: Load Carrying Capacity
Anchorage of hand railing loose due to spalls and delaminations	An evaluation is required to determine the extent of strength reduction

PART 2 – DETAILED VISUAL INSPECTION



FigureA.3. (b) Barrier Wall

Condition State: Good	Performance Deficiency: None
Light scaling	No performance defects

PART 2 – DETAILED VISUAL INSPECTION



Figure A.3 (c) Concrete Railing

<p>Condition State: Poor</p>	<p>Performance Deficiency: Load carrying capacity</p>
<p>Severe spalling of concrete with exposed rebar</p>	<p>Reinforcing steel with considerable portions of its circumference exposed through spalling of concrete will significantly reduce the capacity of the section, due to the loss of bond and corresponding loss of composite action. Barrier system should be replaced with an approved crash-tested system.</p>

PART 2 – DETAILED VISUAL INSPECTION



Figure A.3 (d) Concrete Railing

Condition State: Poor	Performance Deficiency: Load Carrying Capacity
Severe spall on concrete post, with section loss noted on reinforcing steel. Guiderail retrofitted for reinforcement.	Spalls on post and section loss of reinforcing severely limit capacity of barrier system. Retrofitted guiderail provides some reinstatement of capacity, but replacement of barrier with a crash tested barrier system should be planned.