

**Consultation Comments and Responses on CAIS 313-06  
(for Special Provision 313F20, Cross Slope Tolerance Specification)**

Comments received by TCP			
Comment ID	Organization	Comment	Response
N/A	N/A	There is guidance missing regarding the administration of sublots when binder course will be opened to the travelling public for more than 1 month.	<p>The following inspection activities have been added in CAIS for when the binder course is opened to the travelling public for more than 1 month:</p> <ul style="list-style-type: none"> <li>• Determine random subplot locations for the cross-slope measurement. Generate subplot locations for surface and binder courses separately.</li> <li>• Measure the cross slope, within each lot at the determined random subplot locations, as specified. Take the measurements for all binder and surface courses.</li> </ul>